

Set up a calibration curve



To do absolutely	P13-Linearity study of a method
To do if necessary	P11-Detection and quantitation limits
To go further	No procedure identified