


# The powder charging step

In principle two different powder charging processes are used for powder coating:

## ELECTROSTATIC CHARGING

Corona charging of the powder is done by an electric spray gun.



## TRIBO CHARGING

Triboelectric guns charge the powder particles using friction when the particle comes in contact with the walls of the gun and feed tube.

