

SLSR#5 - Work in explosive atmosphere

Updated: April 8, 2025



ND-HSE Managed Documents (All HSE Procedures, Guidelines and Checklists)

- [IND-HSE-SLSR-05-PRO](#) (English version : Master document)
- [IND-HSE-SLSR-05.01-GUI Guideline Work in explosive atmosphere \(SLSR #5\)](#) (English version : Master document)
- [IND-HSE-SLSR-05 Work in explosive atmosphere Field Checklist.xlsx](#) (SLSR assessment translated in various languages)

Regulations and Standards (external and internal)

Regulation	
Process Safety Management of Highly Hazardous Chemicals	OSHA 29 CFR 1910.119 Process Safety Management of Highly Hazardous Chemicals
Welding, Cutting, and Brazing	OSHA 29 CFR 1910.252 Welding Cutting and Brazing
ATEX	DIRECTIVE 1999/92/EC

Standards (Ext and Syensqo)

[All GEC Procedures can be found here...](#)