

# SLSR#5 - Work in explosive atmosphere

Updated: April 8, 2025



## ND-HSE Managed Documents (All HSE Procedures, Guidelines and Checklists)

- [IND-HSE-SLSR-05-PRO](#) (English version : Master document)
- [IND-HSE-SLSR-05.01-GUI Guideline Work in explosive atmosphere \(SLSR #5\)](#) (English version : Master document)
- [IND-HSE-SLSR-05 Work in explosive atmosphere Field Checklist.xlsx](#) (SLSR assessment translated in various languages)

## Regulations and Standards (external and internal)

Regulation	
Process Safety Management of Highly Hazardous Chemicals	<a href="#">OSHA 29 CFR 1910.119 Process Safety Management of Highly Hazardous Chemicals</a>
Welding, Cutting, and Brazing	<a href="#">OSHA 29 CFR 1910.252 Welding Cutting and Brazing</a>
ATEX	<a href="#">DIRECTIVE 1999/92/EC</a>

## Standards (Ext and Syensqo)

*All GEC Procedures can be found here...*